

Valor[®] H5 1100M

Aug 2021

1/1

Mantel Clearances with HeatShift ONLY

WARNING

RISK OF OVERHEATING AND FIRE!
Ensure HeatShift installation is complete AND internal convection baffle is removed (see HeatShift installation) when using these combustible mantel clearances.

Sidewall clearances remain as stated in this installation manual.

HeatShift[™]

NOTE

These Mantel Clearances apply ONLY when HeatShift system is installed

